

J6A/10S Instruction Sheet



<p>Step 1: Strip 26 mm of the jacket and fold braid to cover the jacket. Wrap the drain wire around the cable. The foil length of the wires passing are 3.5mm Min.</p>	<p>Step 2: Insert the wires from the stripped cable into the cap through the hole.</p>	<p>Step 3: Insert the wires into their correct positions based upon the color code.</p>	<p>Step 4: Cut the excess wire off as close to the edge of the cap as possible.</p>	<p>Step 5: Make sure that the arrows on the jack and the cap face in the same direction.</p>	<p>Step 6: Align the cap with the IDC towers and press it into position.</p>	<p>Disassembly Instruction: Step 1: Cut the tie wrap off. Step 2: Remove the grounding wire.</p> <p>Step 3: In order to remove the connector clip, insert a small screwdriver into the slot and rotate to open the wings.</p>
<p>Step 7: Rotate the wings toward each other until they snap closed.</p>	<p>Step 8: Ensure that the drain wire is wrapped around the cable and the strain relief ring for 360° screening connection.</p>	<p>Step 9: Tie wrap the drain wire to the strain relief ring. Do not over-tighten the tie wrap! It should be snug but not so tight that it crushes the wires.</p>	<p>Step 10: Cut the excess tie wrap off as close to the strain relief ring as possible. Ensure that the end of tie wrap is positioned as shown.</p>	<p>Step 11: Insert the grounding wire into the grounding bar on the jack.</p>		